

Montageanweisung / *Installation Guide*
TD 18 UL

1.



Abisolieren / Stripping

2.

T568B

RJ45-PIN	Farbe der Ader (Colour-code)	Pair-Nr.
3	Wei β-Grün (White-Green)	3
6	Grün (Green)	
7	Wei β-Braun (White-Brown)	4
8	Braun (Brown)	
1	Wei β-Orange (White-Orange)	2
2	Orange (Orange)	
4	Blau (Blue)	1
5	Wei β-Blau (White-Blue)	

T568A


RJ45-PIN	Farbe der Ader (Colour-code)	Pair-Nr.
1	Wei β-Grün (White-Green)	3
2	Grün (Green)	
7	Wei β-Braun (White-Brown)	4
8	Braun (Brown)	
3	Wei β-Orange (White-Orange)	2
6	Orange (Orange)	
4	Blau (Blue)	1
5	Wei β-Blau (White-Blue)	

EN 50173

Anschlussbelegungen / Pin assignments


RJ45-PIN	Pairs
1	3
2	
7	4
8	
3	2
6	
4	1
5	

3.




Aufschalten der Aderpaare mit LSA
Werkzeug / *Terminate the wires with
LSA impact tool*

4.



Haken Zugentlastung festdrücken /
Crimp clamp

5.



Deckel festschrauben /
Tighten plate

6.



Abdeckung befestigen /
Fasten the cover plate